


# 붙임1

측정 일시	2015. 07. 16. [1~4] 13:00~17:20, [5~9] 14:30~16:30			
측정 결과	시료번호	측정 지점	측정 결과(f/cc)	유량(l/min)
	1	부지경계선1	0.000	10.2
	2	부지경계선2	0.000	10.1
	3	부지경계선3	0.001	10.2
	4	부지경계선4	0.000	10.2
	5	작업장 주변	0.001	10.2
	6	위생설비입구	0.000	10.1
	7	거주자주거지역1	0.000	10.2
	8	거주자주거지역2	0.000	10.2
	9	음압기	0.000	10.2

### 신한은행포항남금융센터



-  부 지 경 계 선
-  폐기물 보관지점
-  작 업 장 주 변
-  위 생 설 비
-  거주자 주거지역
-  음 압 기

## 현장사진 설명

			
부지경계선1	부지경계선2	부지경계선3	부지경계선4
			
작업장 주변	위생설비 입구	거주자주거지역1	거주자주거지역2
			
음압기			

붙임1

측정 일시	2015. 07. 17. [1~4] 09:10~13:20, [5~9] 10:00~12:00			
측정 결과	시료번호	측정 지점	측정 결과(f/cc)	유량(l/min)
	1	부지경계선1	0.000	10.1
	2	부지경계선2	0.000	10.2
	3	부지경계선3	0.000	10.2
	4	부지경계선4	0.000	10.2
	5	작업장 주변	0.002	10.2
	6	위생설비입구	0.000	10.2
	7	거주자주거지역1	0.000	10.2
	8	거주자주거지역2	0.000	10.2
	9	음압기	0.001	10.2

### 신한은행포항남금융센터



- 부 지 경 계 선
- 폐기물 보관지정
- 작 업 장 주 변
- 위 생 설 비
- 거주자 주거지역
- 음 압 기

## 현장사진 설명

			
부지경계선1	부지경계선2	부지경계선3	부지경계선4
			
작업장 주변	위생설비 입구	거주자주거지역1	거주자주거지역2
			
음압기			